Northeast:

Ursula Randall Wife of Wm Ambler. Born Mar. 10, 1806. Died Mar. 30, 1890.











Southwest:

John Diamond Born Feb. 16, 1799. Died Mar. 11, 1864.

DIAMOND

Southeast:

Lucy Ambler Wife of John Diamond Born Mar. 19, 1803 Died Nov. 22, 1881






Northwest:

William Ambler Born July 4, 1798. Died Nov. 6, 1863.

AMBLER





Condition of Inscription	i: Insc	ription Technique:
□ Excellent	X	Incised
Clear but worn	\overline{X}	Relief
Mostly decipheral	ble	Other (describe):
Mostly undeciphe	erable	
Inscription:		
# of individuals co		
# of carved surfac	ees: 4	
Stonecutter mark:	no	
Gravestone Design Feat	ures/Motifs: none	
Material:		Gravestone Dimensions:
	☐ Granite ☐ Sandstone (4) ☐ Other Stone/Material (describe)	1: 45"h x 13"w x 13"d 2: 8.25"h x 19"w x 19"d 3: 6"h x 22"w x 22"d 4: 16.5" x 27.75"w x 28"d Total Height: 75.75"
Condition of Marker:		
Sound	Stained / Discolor	ed Buried
	Cracked	☐ Broken—# of pieces:
□ Vandalized	Unattached to Bas	e Overgrown (grass / groundcover)
Leaning in Ground	☐ Repaired	Biological (moss / lichen covered)
Missing (base only)	Loose (not in ground,	but marks grave) Displaced (not marking grave)
☐ Mower Scars	Portions Missing	(list): There is a pinhole at the top, indicating some kind of
Other (describe): shifted on	base	missing ornament.
Type of Marker / Monu die, ba	ment: se & cap	
Previous Repairs:		

Remarks / Comments: See also Markers 17A, 17B, 17C and 17D.



FATHER



Marker # 17A Surname(s): Ambler

Condition of Inscription	n: Ins	scription Technique:	
□ Excellent	[Incised	
X Clear but worn]	x Relief	
Mostly deciphera	ıble [Other (describe):	
Mostly undeciph	erable		
Inscription:			
# of individuals of	commemorated: 1		
# of carved surfa	ces: 1		
Stonecutter mark	: no		
Gravestone Design Fea	tures/Motifs: none		
Material:		Gravestone Dimensions:	
	Granite	1: 11.5"h x 10"w x 4"d	
☐ Limestone	Sandstone (2)	2: 4.5"h x 17"w x 10"d	
Zinc Zinc	Other Stone/Material (describe)	Total Height: 16"	
Condition of Marker:			
Sound	Stained / Discol	ored Buried	
Weathered	Cracked	Broken—# of pieces:	
Vandalized	Unattached to B	ase Overgrown (grass / groundcover)	
Leaning in Ground	☐ Repaired	Biological (moss / lichen covered)	
Missing (base only)			
Mower Scars			
Other (describe):			
Type of Marker / Monu			
"die in socket"-style fo	ootstone		
Previous Repairs:			
Remarks / Comments:	See also Marker 17 (Willian	m Ambler).	





Condition of Inscription	on: In	nscription Technique:	
		☐ Incised	
Clear but worn		X Relief	
Mostly decipher	able	Other (describe):	
Mostly undecipl	nerable		
Inscription:			
# of individuals	commemorated: 1		
# of carved surfa	aces: 1		
Stonecutter mar	k: no		
Gravestone Design Fe	atures/Motifs: none		
Material:		Gravestone Dimensions:	
	Granite	1: 11.25"h x 10.25"w x 4"d	
Limestone	Sandstone (2)	2: 4.5"h x 17.5"w x 10.25"d	
Zinc	Other Stone/Materia (describe)	al Total Height: 15.75"	
Condition of Marker:			
Sound	Stained / Discol	olored	
Weathered	Cracked	☐ Broken—# of pieces:	
Vandalized	Unattached to E	Base Overgrown (grass / groundcover	
Leaning in Ground	☐ Repaired	Biological (moss / lichen covered	
Missing (base only)	Loose (not in ground, but marks grave) Displaced (not marking grave)		
☐ Mower Scars			
Other (describe):			
Type of Marker / Mon			
"die in socket"-style f	cootstone		
Previous Repairs:			
Remarks / Comments:	: See also Marker 17 (Ursula	a Randall Ambler).	



AUNT



Marker # 17C

Condition of Inscription: Inscription Technique: Excellent ☐ Incised x Relief Clear but worn Mostly decipherable Other (describe): Mostly undecipherable **Inscription:** # of individuals commemorated: 1 # of carved surfaces: 1 Stonecutter mark: no Gravestone Design Features/Motifs: none Material: **Gravestone Dimensions:** \mathbb{X} Marble (1) Granite 1: 12"h x 10.25"w x 3"d 2: 4"h x 16"w x 9.5"d Limestone Sandstone (2) Zinc Other Stone/Material Total Height: 16" (describe) **Condition of Marker:** Sound Stained / Discolored Buried Cracked Broken—# of pieces: Weathered Vandalized Unattached to Base Overgrown (grass / groundcover) Biological (moss / lichen covered) Leaning in Ground Repaired Loose (not in ground, but marks grave) Lisplaced (not marking grave) Missing (base only) Portions Missing (list): Mower Scars Other (describe): **Type of Marker / Monument:** "die in socket"-style footstone **Previous Repairs:** Remarks / Comments: See also Marker 17 (Lucy Ambler Diamond).

Surname(s): Diamond, Ambler

Across Top and Oriented West:

UNCLE



Condition of Inscription:	Insc	ription Technique:	
Excellent		Incised	
Clear but worn	X	Relief	
Mostly decipherable		Other (describe):	
Mostly undecipheral	ole		
Inscription:			
# of individuals com	memorated: 1		
# of carved surfaces	: 1		
Stonecutter mark: no)		
Gravestone Design Featur	es/Motifs: none		
Material:		Gravestone Dimensions:	
Marble (1)	Granite	1: 11"h x 10"w x 3"d	
Limestone	Sandstone (2)	2: 3.5"h x 16"w x 9.5"d	
Zinc [Other Stone/Material (describe)	Total Height: 14.5"	
Condition of Marker:			
Sound	Stained / Discolor	red Buried	
Weathered	Cracked	Broken—# of pieces:	
☐ Vandalized	Unattached to Bas		
Leaning in Ground	☐ Repaired	Biological (moss / lichen covered	
Missing (base only)			
☐ Mower Scars ☐ Portions Missing (list):			
Other (describe):			
T 435 1 (35			
Type of Marker / Monume			
"die in socket"-style foots	tone		
Previous Repairs:			
Remarks / Comments: See	e also Marker 17 (John Dia	amond).	