

Marker # 388

Surname(s): [Kahler]

Inscription Transcription and Photo(s):

Originally Oriented East:

Freddie.
[Son of]
H. [&] A. Ka[h]le[r]
Died
[Mar. 24, 1872]



Current arrangement of pieces, with socket



Entire stone and socket exposed

Lat / Long: 42° 25' 46.48" N , 83° 29' 12.72" W

Condition of Inscription:

- Excellent
- Clear but worn
- Mostly decipherable
- Mostly undecipherable

Inscription Technique:

- Incised
- Relief
- Other (describe):

Inscription:

of individuals commemorated: 1
 # of carved surfaces: 1
 Stonecutter mark: no

Gravestone Design Features/Motifs: rose

Material:

- Marble
- Limestone
- Zinc
- Granite
- Sandstone
- Other Stone/Material (describe)


Gravestone Dimensions:

Height: 23" (assembled)
 Width: 12.5"
 Thickness: 2"

Condition of Marker:


- Sound
- Weathered
- Vandalized
- Leaning in Ground
- Missing (base only)
- Mower Scars
- Other (describe):
- Stained / Discolored
- Cracked
- Unattached to Base
- Repaired
- Loose (not in ground, but marks grave)
- Portions Missing (list):
- Buried
- Broken—# of pieces: 3 found
- Overgrown (grass / groundcover)
- Biological (moss / lichen covered)
- Displaced (not marking grave)

Type of Marker / Monument:
 die in socket



Type of Tombstone Arch:

discoid



Previous Repairs:

Remarks / Comments: The larger portion of this marker is currently lying face down on the ground. The smaller piece is in the ground, behind the socket.